

## Acceptance Criteria

- ✔ Must be solid enough to walk on
- ✔ Less than 50 ppm Benzene
- ✔ No Greater than 5 pCi/gm total Radium 226 and 228 (Test for in Minnesota no 3 day turn around)
- ✔ No greater than 5 pCi/gm Lead 210
- ✔ Any waste not meeting the RCRA E&P exemption (see Forms & Documents for more information) is subject to testing to confirm its nonhazardous status. This may include TCLP (Toxicity), BTEX, DRO, GRO, flashpoint, corrosivity and reactivity characteristics. Please contact us at (701) 300-1156 for the tests required.

## Wastes Accepted

- ✔ Solidified Drill Cuttings
- ✔ Pit Liners
- ✔ Contaminated Soils from Crude Oil and Natural Gas Drill Locations
- ✔ Tank Farm spills/releases (may require testing or radiation screening)
- ✔ Pipeline leaks (may require testing)
- ✔ Solidified Frac Flowback (may require radiation testing)
- ✔ Construction Debris
- ✔ Production Saltwater spills (may require testing or radiation screening)
- ✔ Transportation spills: Oil, Diesel, Gasoline, Crude (probably requires testing)
- ✔ Underground and Aboveground Storage Tank releases
- ✔ Non-hazardous Industrial Wastes that have a soils type matrix (requires testing)
- ✔ Cement and Asphalt (may require testing)
- ✔ Demolition debris (requires inspection and may require testing)

## Unacceptable Wastes

- ✔ Hazardous Wastes
- ✔ Trash
- ✔ Liquids
- ✔ Putrescible wastes
- ✔ Animal carcasses, wastes or feed wastes
- ✔ Steel, batteries appliances or other readily recyclable materials
- ✔ Electronic wastes (TV's radios etc.)
- ✔ Mercury Containing Devices
- ✔ PCB Oil contaminated materials
- ✔ Ignitable or corrosives
- ✔ Human Wastes
- ✔ Infectious Wastes
- ✔ Regulated Radioactive Wastes

Please contact Environmental Solutions LLC to verify waste acceptance.

Phone: (701) 300-1156 Email:  
disposal@eslandfill.com